









# Assembly instruction








|                                                                                                                         |                                                                                                                            |                                                                                                                         |                                                                                                                          |                                                                                                                          |                                                                                                                           |
|-------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------|
| <p>A</p>  <p>x34</p>                  | <p>B</p>  <p>x34</p> <p>Ø 15*11.5mm</p> | <p>C</p>  <p>x26</p> <p>Ø 8*30mm</p> | <p>D</p>  <p>x15</p> <p>M4*35mm</p>   | <p>E</p>  <p>x11</p> <p>M6*40mm</p> | <p>F</p>  <p>x12</p> <p>M6*25mm</p>  |
| <p>G</p>  <p>x3</p>                  | <p>H</p>  <p>x6</p> <p>M3.5*14mm</p>    | <p>I</p>  <p>x3</p>                  | <p>J</p>  <p>x36</p> <p>M3.5*12mm</p> | <p>K</p>  <p>x6</p>                 | <p>L</p>  <p>x6</p> <p>M3.0*14mm</p> |
| <p>M</p>  <p>x4</p> <p>25*25*3mm</p> | <p>N</p>  <p>x1</p> <p>M4</p>           | <p>O</p>  <p>x3</p> <p>M6.2*48mm</p> | <p>P</p>  <p>x2</p>                   | <p>Q</p>  <p>x2</p> <p>M4*12mm</p>  | <p>R</p>                                                                                                                  |


## Step:1

|                                                                                                                                  |                                                                                                        |                                                                                                               |
|----------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|
| <b>Ⓒ X2</b><br><br>$\phi 8 \times 30 \text{mm}$ | <b>⒩ X1</b><br><br>M4 | <b>⓪ X3</b><br><br>M6.2*48mm |
|----------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|




## Step:2


|                                                                                                                 |                                                                                                                  |
|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| <b>Ⓛ X3</b><br><br>350L 350R | <b>ⓙ X36</b><br><br>M3.5*12mm |
|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|





### Step:3




### Step:4




### Step:5




### Step:6







## Step:7







## Step:8




## Step:9




## Step:10





Step:11

|                                                                                   |                                                                                   |
|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|
| Ⓔ X3                                                                              | Ⓐ X1                                                                              |
|  |  |
| M6*40mm                                                                           | M4                                                                                |






Step:12

|                                                                                     |                                                                                     |                                                                                     |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Ⓔ X4                                                                                | Ⓐ X1                                                                                | Ⓜ X2                                                                                |
|  |  |  |
| M6*40mm                                                                             | M4                                                                                  | 25*25*3mm                                                                           |





## Step:13

|                                                                                   |                                                                                   |                                                                                   |
|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|
| <b>(E)</b> X4                                                                     | <b>(N)</b> X1                                                                     | <b>(M)</b> X2                                                                     |
|  |  |  |
| M6*40mm                                                                           | M4                                                                                | 25*25*3mm                                                                         |




## Step:14

|                                                                                     |                                                                                     |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| <b>(F)</b> X6                                                                       | <b>(N)</b> X1                                                                       |
|  |  |
| M6*20mm                                                                             | M4                                                                                  |






## Step:15





|                                                                                                               |                                                                                                                 |
|---------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|
| <b>(F)</b> X6<br><br>M6*20mm | <b>(N)</b> X1<br><br>M4        |
| <b>(K)</b> X6<br>            | <b>(L)</b> X6<br><br>M3.0*14mm |





## Step:16




## Step:17




Step:18





Step:19





Step:20



# Step:21



Step:22



Step:23

